Firmware Release Notes

Araknis Wireless Access Points

Version 2.0.02



Release Details

Release Date	11/21/2019
Firmware Version	2.0.02
Product SKUs Affected	AN-510-AP-I-AC AN-810-AP-I-AC

IMPORTANT: Reboot your AP prior to applying this firmware.

NOTE: Clear browser cache & settings prior to and after the firmware upgrade.

Added/Removed Features

• Updated user accounts / user access to accommodate password law constraints set by California's IoT security legislation.

Resolved Cloud Issues

- Implemented long-term improvement for persistent OvrC connectivity.
- Enabling/Disabling DST from OvrC now works properly, even if you adjust it multiple times.

Resolved Functional/Local Issues

- Improved functionality for environments that experience periodic loss of internet and/or device connectivity.
- Fixed issue where transmit power was not properly designated as 5GHz and 2.4GHz on the advanced wireless settings page.
- Fixed issue with the 510/810 wherein the help bubble for advanced wireless settings "transmit power" help did not display the correct values.
- Fixed issue wherein pages with large tables and graphics have a double scroll which slowed navigation within the interface